

Maui Resort Swimming Pool

650,000 gallon pool



- Installed 1 Voda Drop in unit October 2018
- 50% chlorine reduction
- 65% reduction in stabilizer daily input
- 90% reduction in body lotion build up
- Water clarity has increased
- Labor reduction